

Sparsholt PC Minutes 15 January 2015 Annex G Highways

Update on Woodman Lane – Carriageway repairs

As you will recall, during the w/c 1 December 2014, HCC carried out extensive repairs at the junction of Stockbridge Road with Woodman Lane and the carriageway repairs were continued, but only as far as the entrance to Lainston House. This was disappointing as the original advice from HCC was that the structural carriageway repairs would extend along Woodman Lane from the Stockbridge Road to Sarum Road.

After numerous enquiries advice was received from HCC, on 24 December, acknowledging that the planned work had not been completed and advising that it would now be re-scheduled to cover the rest of Woodman Lane up to its junction with Sarum Road. No dates for the balance of the work are yet available.

Speed Monitoring on Stockbridge Road (B3049)

Following the report from unsatisfactory exercise carried out by the Police in October, I contacted Andy Smith at HCC and asked that the exercise be repeated in the area of the Stockbridge Road/Woodman Lane junction. The following reply was received on 9 January:

“I will ask our monitoring team to carry out another survey, as it will be quicker than asking the Police to do another one. Having said that, our monitoring team were busy before Christmas with other project-related surveys we asked them to do, but we will ask them to programme this one in now when they can. The Police did say there were some site constraints with placing an automatic counter near the junction, but we will leave that to the monitoring team to locate as best they can.

Andy Smith
Principal Traffic Management Engineer”

Stewart Wooles